The requirements of the consent of	ruer necessitates a review of all sites which, in s	ome cases, requires addi	tional sampling to prepare the		ber of 2020.
Site	Location	Testing Status	Remediation Needed	RAP Submitted	Completed
each Road	Walkway	Completed	No	NA	Yes
rr Elementary School	Soccer Field	Completed	Yes	Yes	Yes
ral Drive	Drainage repair	Completed	No	NA	Yes
ougiello Field	Softball Field	Completed	No	NA	Yes
vight Elementary School	Soccer Field	Completed	Yes	Yes	Yes
irfield Ludlowe High School	Courtyard	Completed	Yes	Yes	Yes
Fairfield Woods Middle School	Lower Soccer Field	Completed	No	NA	Yes
	Parking Area/Plantings Area	Completed	No	NA	Yes
	Upper Soccer Field	Completed	No	NA	Yes
Gould Manor Park	Sidewalk Installation	Completed	Yes	Yes	Yes
	Baseball Fields	Completed	Yes	Yes	Yes
gh Ridge Road	Drainage repair	Completed	No	NA	Yes
lland Hill Elementary School	Soccer Field	Completed	No	NA	Yes
lennings Beach	Area around Water line replacement	Completed	Yes	Yes	Yes
	Playground Grass Area	Completed	Yes	Yes	Yes
lennings Elementary School	Soccer Field	Completed	No	NA	Yes
	Playground	Completed	Yes	Yes	Yes
ke Mohegan	Trail Head Repair	Completed	Yes	Yes	Yes
McKinley Elementary School	Soccer Field	Completed	No	NA	Yes
	Former Playground Area	Completed	Yes	Yes	Yes
ill Hill Elementary School	ADA Sidewalk Installation	Completed	Yes	Yes	Yes
orth Stratfield Elementary School	Soccer Field	Completed	No	NA	Yes
Osborn Hill Elementary School	Baseball Field	Completed	No	NA	Yes
Som mill Elementary School	Drainage repair	Completed	Yes	Yes	Yes
rry Street	Open Space Trail	Completed	Yes	Yes	Yes
Riverfield Elementary School	Baseball Field 1(near Hunter Road/Gym)	Completed	No	NA	Yes
	Baseball Field 2 (near Playscape)	Completed	No	NA	Yes
	Grass Area near Parking Lot	Completed	Yes	Yes	Yes
uthport Beach	Curb Repair	Completed	Yes	Yes	Yes
nset Avenue	Curb Installation	Completed	Yes	Yes	Yes
Fomlinson Middle School	Back Drainage repair	Completed	No	NA	Yes
	Front Drainage Repair	Completed	No	NA	Yes
wn Hall	Soccer Field	Completed	Yes	Yes	Yes
nxis Hill	Soccer/Baseball Field	Completed	No	NA	Yes
Yacht Yard	Curb Repair	Completed	Yes	Yes	Yes
Burroughs	Soccer Field 1	Completed	Yes	Yes	Yes
	Soccer Field 2	Completed	No	NA	Yes
Fire Training Center	Under Burn Building	Completed	No	NA	Yes
	Under Stormwater System	Completed	No	NA	Yes
	Under Tank	Completed	No	NA	Yes
ratfield Road	Tree Repair	Completed	No	NA	Yes
Senior Center	Gazebo and Patio Installation	Completed	No	NA	Yes
	Soccer Field	Completed	Yes	Yes	Yes
South Pine Creek Rec. Area	Football (Sullivan/Multipurpose)	Completed	Yes	Yes	Yes
	Soccer Field 1	Completed	Yes	Yes	Yes
mp Mortar	Catch basin repair	Completed	Yes	No	
II Hill Road	Sidewalk Installation	Completed	Yes	No	
lside Road	Curb Project	Completed	Yes	No	
Hoydens Hill Area	Barn at the Shooting Range	Completed	Yes	No	
	Shooting Range	Completed	No	NA	Yes
	Trail	Completed	No	NA	Yes
ank Rice Senior Trail/Oldfield/Old Dam Rd Open Space	Open Space Trail	Completed	Yes	No	
Penfield Pavilion	Parking Lots	Completed	Yes	Yes	
	Building Area	Completed	Yes	Yes	
nald Drive	Curb Installation	Completed	Yes	No	
nith Richardson	Cart Path and Driveway Repair	Completed	Yes	No	

Last Updated 2/28/2023

RAP-Remediation Action Plan- A plan outlining how remediation will occur prepared by the LEP and submitted to DEEP per the Consent Order. IR- Investigation Report-Summary of testing results prepared by the LEP and submitted to DEEP per the Consent Order. RAR- Remediation Action Report- LEP verifies remediation work done was completed according to the RAP.

LEP- Licensed Environmental Professional Yes - Final reports submitted to DEEP