This spreadsheet represents the current status of the areas where fill from the fill pile was used in relation to the requirements of consent order entered into with CT DEEP in October of 2020.

	rder necessitates a review of all sites which, in so				
Site	Location	Testing Status	Remediation Needed	RAP Submitted	Completed
Beach Road	Walkway	Completed	No	NA	Yes
Burr Elementary School	Soccer Field	Completed	Yes	Yes	Yes
Coral Drive	Drainage repair	Completed	No	NA	Yes
Dougiello Field	Softball Field	Completed	No	NA	Yes
Dwight Elementary School	Soccer Field	Completed	Yes	Yes	Yes
Fairfield Ludlowe High School	Courtyard	Completed	Yes	Yes	Yes
Fairfield Woods Middle School	Lower Soccer Field	Completed	No	NA	Yes
	Parking Area/Plantings Area	Completed	No	NA	Yes
	Upper Soccer Field	Completed	No	NA	Yes
Gould Manor Park	Sidewalk Installation	Completed	Yes	Yes	Yes
	Baseball Fields	Completed	Yes	Yes	Yes
High Ridge Road	Drainage repair	Completed	No	NA	Yes
Holland Hill Elementary School	Soccer Field	Completed	No	NA	Yes
Jennings Beach	Area around Water line replacement	Completed	Yes	Yes	Yes
	Playground Grass Area	Completed	Yes	Yes	Yes
Jennings Elementary School	Soccer Field	Completed	No	NA	Yes
	Playground	Completed	Yes	Yes	Yes
Lake Mohegan	Trail Head Repair	Completed	Yes	Yes	Yes
McKinley Elementary School	Soccer Field	Completed	No	NA	Yes
	Former Playground Area	Completed	Yes	Yes	Yes
Mill Hill Elementary School	ADA Sidewalk Installation	Completed	Yes	Yes	Yes
North Stratfield Elementary School	Soccer Field	Completed	No	NA	Yes
Osborn Hill Elementary School	Baseball Field	Completed	No	NA	Yes
	Drainage repair	Completed	Yes	Yes	Yes
Perry Street	Open Space Trail	Completed	Yes	Yes	Yes
	Baseball Field 1(near Hunter Road/Gym)	Completed	No	NA	Yes
Riverfield Elementary School	Baseball Field 2 (near Playscape)	Completed	No	NA	Yes
	Grass Area near Parking Lot	Completed	Yes	Yes	Yes
Southport Beach	Curb Repair	Completed	Yes	Yes	Yes
Sunset Avenue	Curb Installation	Completed	Yes	Yes	Yes
Tomlinson Middle School	Back Drainage repair	Completed	No	NA	Yes
	Front Drainage Repair	Completed	No	NA	Yes
Town Hall	Soccer Field	Completed	Yes	Yes	Yes
Tunxis Hill	Soccer/Baseball Field	Completed	No	NA	Yes
Ye Yacht Yard	Curb Repair	Completed	Yes	Yes	Yes
Burroughs	Soccer Field 1	Completed	Yes	Yes	Yes
	Soccer Field 2	Completed	No	NA	Yes
Fire Training Center	Under Burn Building	Completed	No	NA	Yes
	Under Stormwater System	Completed	No	NA	Yes
	Under Tank	Completed	No	NA	Yes
Stratfield Road	Tree Repair	Completed	No	NA	Yes
Senior Center	Gazebo and Patio Installation	Completed	No	NA	Yes
	Soccer Field	Completed	Yes	Yes	Yes
South Pine Creek Rec. Area	Football (Sullivan/Multipurpose)	Completed	Yes	Yes	Yes
	Soccer Field 1	Completed	Yes	Yes	Yes
Smith Richardson	Cart Path and Driveway Repair	Completed	No	NA	Yes
Samp Mortar	Catch basin repair	Completed	Yes	Yes	Yes
Mill Hill Road	Sidewalk Installation	Completed	Yes	Yes	Yes
Hoydens Hill Area	Barn at the Shooting Range	Completed	Yes	Yes	Yes
	Shooting Range	Completed	No	NA NA	Yes
	Trail	Completed	No	NA NA	Yes
Ronald Drive	Curb Installation	Completed	Yes	Yes	Yes
Hillside Road	Curb Project	Completed	Yes	Yes	Yes
Frank Rice Senior Trail/Oldfield/Old Dam Rd Open Space	Open Space Trail	Completed	Yes	Yes	.03
Tennis Facility	Rear Drainage/Rain Garden	Completed	Yes	Yes	
•	Parking Lots	Completed	Yes	Yes	
Penfield Pavilion	Building Area	Completed	Yes	Yes	
	Building Area	Completed	Yes	Yes	1

Last Updated 09/06/2023

RAP-Remediation Action Plan- A plan outlining how remediation will occur prepared by the LEP and submitted to DEEP per the Consent Order.

IR- Investigation Report-Summary of testing results prepared by the LEP and submitted to DEEP per the Consent Order.

RAR- Remediation Action Report- LEP verifies remediation work done was completed according to the RAP.

LEP- Licensed Environmental Professional Yes - Final reports submitted to DEEP